


Lantern Photos





An aerial photograph looking down at a large, green-painted metal lantern roof. A flag pole runs diagonally across the roof from the bottom left towards the top center. The roof is composed of several large, flat panels separated by seams. In the background, a city street with various buildings and a river is visible. A text box with red text is overlaid on the left side of the roof.

Numerous dents
on lantern roof and
base of flag pole


Ceiling inside lantern
needs to be replaced






Photo of steel structure inside lantern
roof. The copper doesn't appear to be
supported or attached to the structure
sufficiently






Copper is not continuously supported so it is collapsed in some areas


Dents, tears, and split seams









Tears and holes in copper



Holes in copper








The copper appears to be sagging
due to potential structural issues

Exposed fasteners are
rusting and will eventually fail






Evidence of
ponding water

Copper is not supported
and therefore dented and
collapsing in areas


































Missing spindle



